

Schwindt and Company



Squirrel's nest in attic.



Squirrel's nest in attic.



Remains of squirrel in attic floor. This house must have stunk for a while.



Condensation problem in attic. Some mold growth. (Unsafe)

Schwindt and Company



Mice in the attic.



Leak stains on attic side walls, due to leaking step flashing.



Mouse holes in attic insulation.