

Schwindt and Company



Rot damage to stair carriage, due to extensive water entry.



Mold growth on basement walls.(Unsafe)



Extensive water seepage to basement.



Mold growth on basement walls. (Unsafe)

Schwindt and Company



Opossum in crawl space.



Crawl space - No vapor barrier on ground, loose ducts and wires on ground, trash and debris.



Insulation installed up side down. Insulation missing and falling.



Abandoned oil tank needs to be removed. Falling insulation.