

Schwindt and Company



Failing flue liner, not safe for use.



Metal fireplace flue separating. Attic view. (Unsafe)



Old through-the-house chimney has no liner installed. (Unsafe)