


Schwindt and Company



Leaking roof has caused rot damage to walls and mold growth. (safety)



Bathroom plumbing leak is damaging kitchen ceiling.



Door frames not square due to floor settlement. Structural issues.



Smoke on fireplace face, due to poorly drafting chimney flue.